SURVEY PARTY: JMW-RH-(RL in NOTES)

322

SURVEY NO. 12449
TIES #6

DATE: 3-12-82

SURVEY FIELD NOTES

SHEET NO. ____ OF ____

93

SEE SHEET #7

NOTE: Original ℄ of LINCOLN AVE was on the 1/4 Section Line and original ℄ of TULARE AVE was on the 1/4 1/4 Section Line per TRACT No 9224 M.B. 180-7

SURVEY OF: ℄ TIES TO 1/4 1/4 SEC 6 & ℄ LINCOLN & TULARE BURBANK

CLIENT: P.M. No 14490

S 26.17 TO ℄ LINCOLN @ KENNETH

Set L&T LS2996

3.5

Set L&T LS2996

13.8

53.60

51.10

38.96

36.75

89°41'35"

N 0°18'25" E

℄ TULARE AVE
per BURBANK CITY TIES

Fd S&W LS2996
per TR 31960
SM.18 971-12A 13, F
FC. S.D. FB. 2302-73

TO 1/4 1/4 COR 1327.63

0.44

1/4 1/4 Section Line

Set S&W
LS2996

53.505

39.12

39.00

41.86

42.505

54.19

B.C.R.

Fd Lead & Rivet
BURBANK CE FB
140-59 (?)
305-46
Flood Control FB
FCSD 2302-73
DIV HWYS FB
A24.001-72

Set L&T
LS2996

5.12

13.8

E.C.R.

℄ LINCOLN AVE
per BURBANK
CITY TIES

1/4 Section Line

TO ℄ OF SECTION 1326.18

P.M. #14490
WEBER AIRCRAFT

MOLLENHAUER, HIGASHI & MOORE, INC.
LAND SURVEYORS AND CIVIL ENGINEERS
453 SOUTH SPRING STREET, LOS ANGELES, CALIFORNIA 90013
PHONE: (213) 624-2661