

NO SCALE

SET SPK'W AT REC. DIST. NORTH OF ROBERTS PLACE PER TRACT NO. 32330 MB 854-89-90

F.L. TRACK, NO REF. SET NAIL TAG LS5748

F.L. PK NAIL, NO REF.

o = SET. L.F. TAG LS5748 UNLESS OTHERWISE NOTED.

ROGERS

PL.

129.65'

(89-03-27 TR. 32330) 89-03-27 M

F.L. SPK'W IN P.W. PER CALTRANS F.B. A-24.001 PG. 139 AND CITY BURB. FB 314-103

F.L. of R.M.'S ON M.H. RIM (PM'S ARE NOT TAN. TO E) PER CALTRANS FB A24.001 PAGE 139 AND BURB. FB 314-103, FITS TIES PER BURB. FB 302-35

GRISMER 302.96'

F.L. CONC. NAIL NO REF.

F.L. 6" x 6" x 16" HOLE IN PAVT. DUG BY OTHERS. F.L. NOTHING IN HOLE. SET SPK'W LS5748 RECORD DIST. FROM ROBERTS PLACE AND FROM BUR. I-2A TRAN. MON PER TR. NO. 38665 MB 956-80-81

SAN

FERNANDO

F.L. BUR I-2A TRAN. MON. PER TR. NO. 38665 MB 956-80-81

F.L. NAIL SHANK BLUD. NO REF.

PWFB 1818

458


CORNER RECORD

Document Number

City of BURBANK

County of Los Angeles, California

Brief Legal Description CENTERLINE MONUMENTATION AND CENTERLINE TIES.



CORNERTYPE

Govt. Corner [] Control [x]
Meander [] Property []
Rancho [] Other []
Date of Survey DEC. 24 2007

COORDINATES (Optional)

N.
E.
Zone NAD27 [] NAD83 []
NAD83 Epoch
Elev.
Vert. Datum: NGVD29 [] NAVD88 []
Meas. Units: Metric [] Imperial []

Corner - Left as found [x] Found & tagged [x] Established [] Reestablished [x] Rebuilt []

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:


SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance

with the Land Surveyors' Act on DEC. 24 2007

Signed [Signature] P.L.S. or R.C.E. No. 5748



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 22 2008 FEB 05 2008

and examined and filed FEB 19 2008

Signed [Signature] P.L.S. or R.C.E. No. 6388

Title: DEPUTY COUNTY SURVEYOR

County Surveyor's Comment

