

FB 339 P.35

M = MEASURED

R = RECORD



NOT TO SCALE

TULARE AVE

14' 2' 9' 15'

RIGHT OF WAY

217 CURB

45

(59.25 R)
59.24 M

47.07 M

40'

CENTERLINE

SAN FERNANDO BLVD

70'

38.50 M + R

21.92 M
(21.90 R)

48.49 M
(48.50 R)

30'

CURB

RIGHT OF WAY

Δ = SET NAIL + TAG LS 6498

● = FOUND NAIL + TAG LS 2996 (PER FB 322 PG 85)

⊙ = FOUND SPIKE WITH PUNCH + WASHER LS 2996
(PER FB 322 PG 85)

CORNER RECORD

PWFB 1818


864

City of BURBANK

Document Number _____
County of LOS ANGELES, California

Brief Legal Description SAN FERNANDO BLVD AND TULARE INTERSECTION

20463



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/15/2016

COORDINATES(Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NADV88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.
The purpose of this corner record is to perpetuate the existence of the monument(s) located at the intersection of
San Fernando Road and Tulare road in Burbank, California.

A description of the physical condition of the monument as found and as set or reset: See reverse for ties.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3-22, 2016.

Signed [Signature] P.L.S. or R.C.E. No.: 6498



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 28 2016 and examined
and filed APR 21 2016

Signed [Signature] P.L.S. or R.C.E. No.: 6388

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

