



# CORNER RECORD


City of BURBANK

Document Number \_\_\_\_\_

County of Los Angeles, California

BEACHWOOD DRIVE & CHANDLER BOULEVARD (SOUTH ROADWAY)

Brief Legal Description \_\_\_\_\_



### CORNER TYPE

Govt. Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 1/16/17

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NAVD88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found & tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

RESET ON N-S TIE LINE AT RECORD DISTANCE

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

FOUND POINTS IN GOOD CONDITION

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance  
with the Land Surveyors' Act on FEBRUARY 2, 2017

Signed David Lindell P.L.S. or R.C.E. No. LS 4016



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_

and examined and filed \_\_\_\_\_

Signed \_\_\_\_\_ P.L.S. or R.C.E. No. \_\_\_\_\_

Title: \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_