

FB-334 P.96

| CORNER RECO | | Document Number | | | |
|---|--|---------------------|-----------------------|--|---------------|
| ty of County of Los Angeles, California | | | | | |
| Brief Legal Description | CENTERLINE TIES | : GLENOAKS] | BOULEVARD & | CAMBRIDG | E DRIVE |
| | Government Corner Meander Rancho Date of Survey <u>D5</u> | □ Property □ Other | N. E. Zone NAD83 Epoc | NGVD29 | NAVD88 |
| Corner - Left as | found Found and ta | agged Estab | lished Reesta | blished 🏻 | Rebuilt 🗆 |
| Identification and type of c | orner found: Evidence used | to identify or pro | cedure used to establ | lish or reestablis | h the corner: |
| | REESTAB'D BY IN | NTERSECTION | OF TIES | | |
| A description of the physic | al condition of the monume | | set or reset: | | |
| | SURVEYOR'S STATEM prepared by me or under n MAY 31, 2000 | ny direction in con | formance with | | DAVID L. |
| the land Summover's Act of | Zindell P.L.S or R | | 016 PIRES 6-30-04) | Costs of the costs | No L. S. 4016 |
| CO | UNTY SURVEYOR'S STA | ATEMENT | | | OF CALIFORN |
| This Corner Record was re | ceived | | | | |
| and examined and filed | | | | | |
| Signed | P.L.S or R | .C.E. No | | | |
| Title | | | | | |
| County Surveyor's Com | ment | | | | ~ |
| | | | | | |
| | | | | | |

Page 1 of 2

Borpels-1297