

FB-335 P. 251



N. T. S.

FND L & R IN WALK
CHIS "T"

SET L & TAG, PLS 5691,
IN WALK; TANGENT TIE;
CHISELED "T".

FND SPK. AND C E
WASHER AT ANG. PT.
UNDER AC SLURRY;
RE-PUNCHED PER TIES.

SET L & TAG, PLS 5691,
IN BACK WALK; TANGENT
TIE; CHISELED "T".

FND L & TAG, LS 7310,
IN CURB, NO REF.
TAN. TIE; CHIS "T"

FND L & TAG, LS 7310,
IN CURB, NO REF.
TAN. TIE; CHIS "T"

FND SPK. AND C E WASHER;
MEAS. FND TAN TIES.

FND L & C E TAG IN
CURB ON C/L PROD.

PARKSIDE AVE.

FND L & TAG, LS 7310,
IN CURB, NO REF.
TAN. TIE; CHIS "T"

FND L & R IN WALK
CHIS "T"

FND L & TAG, LS 7310,
IN CURB, NO REF.
TAN. TIE; CHIS "T"

**BOB HOPE DRIVE
(CATALINA ST.)**

REFERENCE: CEFB 285-1

DATE: MARCH 9, 2003
SURVEYED BY: J. P. OSTLY
P. L. S. 5691

CORNER RECORD

Document Number


220

City of BURBANK

County of Los Angeles, California

MONUMENT

Brief Legal Description BOB HOPE DR. (CATALINA ST.) & PARKSIDE AVE. - PRESERVATION



CORNER TYPE

Govt. Corner Control
 Meander Property
 Rancho Other
 Date of Survey MARCH 9, 2003

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found & tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

see plat;

distances measured horizontal;

A description of the physical condition of the monument as found and as set or reset:

see plat;

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance

with the Land Surveyors' Act on April 6, 2003

Signed [Signature] P.L.S. or R.C.E. No. 5691



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 10 2003

and examined and filed APR 29 2003

Signed [Signature] P.L.S. or R.C.E. No. _____

Title: DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



SM 6 4-23-03