

APN 2460-003
TG 533-66

JN 11159

CORNER RECORD

Document Number _____

City of BUFFALINK

County of Los Angeles, California

Brief Legal Description INTERSECTION OF EAST AVE + BETHANY RD



CORNERTYPE

Govt. Corner Control

Meander Property

Rancho Other

Date of Survey 12/13/08

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner - Left as found Found & tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset: _____

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance
with the Land Surveyors' Act on DEC. 18 2008

Signed [Signature] P.L.S. or R.C.E. No. 5748



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title: _____

County Surveyor's Comment _____