

## CORNER RECORD

Document Number .

City of —————		C	ounty of L	.os Angeles	, Califo	rnia				
Brief Legal Description	BUENA VISTA	STREE	T & K	ITTRIDGE	STR	EET				~
		ERTYPE	011		N COORDINATES (Optional) E NAD27  NAD83					
	Govt. Comer Meander		Control Property		NAD8	3 Epoch _			NAD83	
	Rancho Date of Survey	□ 8/26	Other <b>5/10</b>	<b>¤</b> –	Vert. D	Datum: Units:	NGVD	29 🗆	NAVD88 Imperial	
Corner - Left as found	d ☐ Found	& tagged		Established		Reesta	blished		Rebui	t 🍳
Identification and type of cor	ner found: Evidenc	e used to	identify	or procedur	e used	to estab	olish or re	estab	olish the co	orner:
SEE P	PLAT									
A description of the physical of	condition of the mor	nument a	s found a	nd as set or	reset: .					-
SEE_F	PLAT									
SURVE	YOR'S STATEMEN	т						10	LAND SUR	
This Corner Record was prepared	ared by me or unde	r my direc	tion in cor	nformance			(3) 17	7	D L. LINDEI	" "
with the Land Surveyors' Act o	on	AUGUST		2010 .					LS 4016	
Signed Marie Z. Zin	<i>sell</i> P.L.S.	or R.C.E	. No	L <del>S 4016</del>			No.	TATE	OF CALIFO	
COUNTYS	SURVEYOR'S STATI	EMENT							CAL	
This Comer Record was received	/ed									
and examined and filed										
Signed	P.L.\$.	or R.C.E	. No							
Title:										
County Surveyor's Comment										
82-0029 DPW Rev. 11/00 Borpels-1297 APN	N/A	_	Page 1 of	72 T.O	<b>3</b>	3-D-7				