

CORNER RECORD City ofBURBANK			Document NumberCounty of Los Angeles, California						
	VE AVENUE								
	CORNER TYPE Govt. Corner Meander			Control	COORDINATES (Optional) N E Zone NAD27 □ NAD83 □				_
	Rancho Date of Survey		Other	X	NAD83 Elev Vert. Da	Epoch_ atum: Units:	NGVD29	NAVD88	_
Corner - Left as found	☐ Found	& tagged	1 🗆	Established		Reesta	ablished 🗌	Rebui	lt 🔀
dentification and type of corner	found: Evidence	e used to	identify o	or procedure	e used	to estab	lish or reestal	blish the co	orner
SEE PLAT							,		
	···								
description of the physical cond	dition of the mor	nument as	s found ar	nd as set or	reset:_				_
SEE PLAT									
SEE PLAT					<u></u>			- <u>-</u>	
SURVEYO	OR'S STATEME	NT						1AND	
This Corner Record was prepared with the Land Surveyors' Act on	•	r my dired JUNE		nformance 014			DAV	LAND SUR	LEYOR
Signed David Z. Zindell P.L.S. et R.G.E. No. LS 4016								LS 4016	
•	IRVEYOR'S STA						NATE .	OF CALIFO	Ret !
This Corner Record was received	<u> </u>		_				1		Ì
and examined and filed								EA!	/
Signed	P.L.S. or	r R.C.E. N	1o				V		1
Title:							-		
County Surveyor's Comment_						_			
									
									

Page 1 of 2