

Document Number _____ County of Los Angeles, California CLYBOURN AVE. & HATTERAS STREET **Brief Legal Description COORDINATES (Optional) CORNER TYPE** Control Govt. Comer E. __ NAD27 🛘 NAD83 □ Zone . **Property** Meander П NAD83 Epoch __ Elev. Other Rancho П NGVD29 □ NAVD88 Vert. Datum: 3/23/10 Date of Survey Meas. Units: Metric Imperial Rebuilt X Reestablished Established Left as found Found & tagged Corner -Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: SEE PLAT A description of the physical condition of the monument as found and as set or reset: SET S&W LS 4016 AFTER CONSTRUCTION SURVEYOR'S STATEMENT DAVID L. LINDELL This Corner Record was prepared by me or under my direction in conformance LS 4016 APRIL 12, 2010 with the Land Surveyors' Act on _____ Signed Zindell P.L.S. or R.C.E. No. LS 4016 COUNTY SURVEYOR'S STATEMENT This Corner Record was received_____ and examined and filed ______ Signed _____ P.L.S. or R.C.E. No.____ County Surveyor's Comment

82-0029 DPW Rev. 11/00

N/A

563-B-1

T.G.

Page 1 of 2