
Document Number FB 339 P. 163



CORNER RECO	C	Document NumberCounty of Los Angeles, California							
Brief Legal Description TULARE	AVENUE &		-	_	is, Call	IOITIIA			
	CORNE				С	OORDIN	IATES (O	ptional)	
			Control		N			'	
├- -	Meander		Property	 '	Zone_	R Enoch	NAD27	Z□ NAD8	3 🛮
	Rancho	– '	Other	×	Elev.	atum:			
	Date of Survey	6/10/	16	_	Meas.	units:	Metric	NAVD8	. —
Corner - Left as found	Found 8	tagged		Established		Reesta	blished [Ret	ouilt 💢
Identification and type of corner fo					e used	to establ	ish or ree	stablish the	corner:
A description of the physical condi	tion of the monu	ment as	found ar	nd as set or	reset:_				
ALL FOUND TI	E POINTS IN	GOOD	COND	ITION					
·				· · · · · · · · · · · · · · · · · · ·					
SURVEYO	R'S STATEMEN	 IT							
			ion in co	nformance				LAND S	URVEZ
This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on								AVID L. LINE	DELL DELL
				4046				LS 4016	
Signed David Z. Zinde	P.L.S. or R	I.O.E. . No.		4016			(S)		
COUNTY SUF	RVEYOR'S STAT	FEMENT					1	TE OF CALL	FOR!
This Corner Record was received_									
and examined and filed									
Signed									1
Title:									
County Surveyor's Comment									
County Surveyor's Comment									
County Surveyor's Comment									