

CORNER RECORD


City of BURBANK

Document Number _____

County of Los Angeles, California

GRIFFITH PARK DRIVE & CHANDLER BOULEVARD (SOUTH ROADWAY)

Brief Legal Description _____



CORNER TYPE

Govt. Corner Control
 Meander Property
 Rancho Other
 Date of Survey 1/31/17

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found & tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

RESET BY TIES

A description of the physical condition of the monument as found and as set or reset: _____

FOUND POINTS IN GOOD CONDITION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance
FEBRUARY 2, 2017

with the Land Surveyors' Act on _____

Signed David L. Lindell P.L.S. or R.C.E. No. LS 4016



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title: _____

County Surveyor's Comment _____