

FB 340 P. 41



ALL TIES PER PWFB
1618-591, 592
(CEFB 338-552)
DESTROYED

SET L & TAG
LS 4016 IN C.B.
9.0' W/O ECR
2.0' B/O C.F.

STREET

FD. C.E. TAG
IN C.B. 1.2'
B/O C.F.

FD. C.E. S&W PER
PWFB 1618-591, 592
(C.E.F.B. 338-552)
RESET S&W LS 4016

FRANKLIN

AVENUE

58.22'

54.42'

54.335'

51.435'

SET L & TAG
LS 4016 IN C.B.
0.7' B/O C.F.

FD. C.E. TAG
0.095' SE/O
TAN TIE

ROSE

CORNER RECORD


Agency Index _____

Document Number _____

City of BURBANK

County of LOS ANGELES, California

Brief Legal Description ROSE STREET & FRANKLIN AVENUE



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey 9/19/19

Date of Survey _____

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref: 8766(d) 8771 8773 Other: _____

Corner/Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s) :

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on SEPTEMBER 20, 2019
 Signed David L. Lindell P.L.S. or R.C.E. No. LS 4016



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____,
 and examined and filed _____,
 Signed _____ P.L.S. or R.C.E. No. _____
 Title _____
 County Surveyor's Comment _____

A.P.N.: N/A

T.G. 563-D-5